

ST JOHN-IN-BEDWARDINE CHURCH TOWER APPEAL

Tower Work Progress 7th April 2011



Climbing the
scaffold tower...

Don't look down!

The rotten wood
is removed. This
is death-watch
beetle damage...





... and this is
wet rot.




Woody finds more rotten timber.
The whole wall plate and timber sub-structure will
need to be replaced.



Here comes the new timber!

The stout beams for the new wall-plate are hoisted to the tower roof.

It takes four men to lift each piece!





The stonemason has cut a hole to take the new steel support, which is to hold up the main roof beam.

Woody found this old bottle, cocoa tin and pen-knife on the top of the roof-beam! Does anyone recognise them?

